

Interior Electrics

Advanced key Keyless entry doesn't work

Problem

Keyless entry and start with "Start-stop sensor" don't work. Remote control functions and vehicle start work correctly.

Technical background

The authorisation control unit is incorrectly diagnosing faults in the Kessy aerials. This happens if you have software version 130 or component complaint in the vehicle authorisation control unit with hardware version H03.

Production change

Control units with software 140 and hardware H04 from Chassis No. WAUZZZ4E*5N005002 on control units with software 140 and hardware H04.

Resolution

Read the memory. If in the address code 05 (vehicle authorisation system/ 05 - Access / Start Auth) all Kessy aerials are logged with the complaint numbers listed in the table or the complaint "0003 Control unit complaint in the circuit", The resolution is to update the vehicle authorisation control unit to the above levels

Fault List

00179	Aerial driver side -R134
00180	Aerial passenger side -R135
00181	Bumper aerial -R136

Interior Electrics

00182	Boot aerial -R137
00183	Aerial -1- passenger compartment -R138

Unique solution ID: #1025

Author: Nick

Last update: 2013-02-22 21:36